## FOR OFFICIAL USE ONLY

## U.S. Army Accident Information Class A Ground Accidents for 1 October 2015 to 7 July 2016 Primary Accident Type is PMV-2 and Vehicle Type is Motorcycle CASES=22

No	Case Number	Description
1	20160707001	Soldier was discovered deceased after his motorcycle had left the road and struck a telephone pole. Soldier was on leave, current in training, and was wearing a helmet.
2	20160702001	Soldier lost control on a freeway exit ramp and crashed, falling over the ramp. He was wearing a helmet but declared deceased at the scene.
3	20160628002	Soldier collided with Ford F150 pick-up truck when it entered the highway in front of him. Soldier was trained and wearing full PPE but was pronounced dead at the scene.
4	20160625001	Soldier struck a curb when his sport bike became unstable while he was accelerating. Soldier was wearing full PPE but sustained fatal injuries in the crash.
5	20160605001	Soldier was operating his POM at night when he struck a black cow that was in the range road in the wake of recent flood conditions. Soldier was wearing full PPE but suffered fatal injuries as a result.
6	20160526001	Soldier lost control while operating his POM on a curve and struck a roadside tree. Soldier was trained wearing PPE but was pronounced deceased at the scene.
7	20160523002	Soldier crashed into the rear of a van as it was turning left in front of him as he was attempting to pass. Soldier was wearing PPE but was pronounced dead at the scene.
8	20160518001	Soldier collided with the rear end of a pick-up truck while riding a POM while on leave at this HOR.
9	20160509001	Soldier collided with the rear end of a POV-van while riding. Soldier was wearing full PPE but died at the scene.
10	20160312001	Soldier fell off his bike while negotiating a highway access ramp on a major thoroughfare and was struck the vehicle trailing him. He was wearing full PPE but was pronounced dead at the scene.
11	20160213008	Soldier was discovered by his co-rider after having crashed on his POM. He passed from his injuries on 13 Apr 16.
12	20160118001	Soldier struck a depression in the pavement while riding his motorcycle, lost control, and crashed. He was pronounced dead at the scene. Police report that speed and no helmet use were contributing.
13	20160116001	Soldier was operating his POM when he was struck by a 2000 Honda Accord that crossed the median and entered his path of travel. Soldier was wearing full PPE and trained but was pronounced dead at the scene.
14	20151231001	. Soldier was reportedly struck by a civilian vehicle while operating his POM. Soldier was trained, licensed, and wearing full PPE but suffered fatal injuries and was pronounced dead at the scene.
15	20151226001	Soldier was traveling on the interstate when he crashed for undetermined reasons and was fatally injured. Local authorities report that he was not wearing a helmet.
16	20151220001	Soldier was riding in the vicinity of the city limits when he apparently lost control, left his lane, and crashed. Soldier was pronounced dead at the scene.
17	20151210002	Soldier was on his motorcycle in the city limits when he collided with a vehicle that reportedly pulled into his lane of travel. Soldier was wearing PPE and was trained but was pronounced dead of his injuries upon arrival at the local hospital.
18	20151203001	Soldier was operating his Honda CBR 600 sport bike when he reportedly attempted to pass an 18-wheeler as it was turning at an intersection and struck the trailer broadside. The Soldier was licensed, trained, and was wearing proper PPE but was pronounced dead at the scene.

19	20151112002	Soldier was operating his POM when he reportedly lost control on a left-hand turn and struck a guard rail. He was transported to the ER for treatment of head injuries. He was removed from life support two days later. 14 Soldier was wearing full PPE and had completed the MSF requirements,
20	20151029001	Soldier was attempting to pass another vehicle from the opposing lane when he lost control and crashed into the guard rail. Soldier was wearing PPE and MSF-trained. Road conditions were reported as damp.
21	20151022002	Two Soldiers were involved in a collision on the interstate highway while riding motorcycles together. Both were wearing PPE and were currently trained but one Soldier was fatally injured as a result.
22	20151003006	Soldier reportedly lost control of his motorcycle while proceeding back to his drill location from lunch. He was trained and wearing PPE but succumbed to his injuries on 5 Dec 15, while still hospitalized. Police reported cited speed as excessive for road conditions.